VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicle

CAMPAIGN No.	GAI-2745	DATE	Nov.14,2018		
MANUFACTURER	TADANO LTD.				
DESCRIPTION OF DEFECT	Due to inadequate waterproofness of the engine cover inspection door lock there is a chance of rainwater, etc, entering the engine room and accumulating on top of the engine. Therefore, with continued use in this condition, there is a risk of the fuel piping on top of the engine corroding and in the worst cases leading to fuel leaking out.				

TYPE	COMMERCIAL NAME		MODEL YEAR RECALLED	NUMBER OF VEHICLE
FAUN	RTF360G-6	2009-2012		29
			TOTAL	29