
VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

	Domestic (Import Vehicles)			
CAMPAIGN No.	GAI - 2763	DATE	7 th/Dec/2018	
MANUFACTURE	LOTUS CARS Pic			
	(Japanese Importer :LCI Limited)			
DESCRIPTION OF DEFECT	Assembly of the steering column cartridge (which absorbing the collision energy when crash event) at the production line became inappropriate. For this reason, parts with insufficient tightening torque of the fixing screw were confirmed. As a result, if the screw loosens and falls off, there is a possibility that collision energy cannot be absorb at the time of crash event.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LOTUS	EVORA GT410 SPORT	2018	1
	EVORA 400	2018	1
		TOTAL	2

【記入例】

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN



TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
		製作年のみの記載。	
		TOTAL	

Domestic Vehicles:日本国内車両

Import Vehicles:輸入車両 CAMPAIGN No.:届出番号

DATE: 届出年月日

MANUFACTURE: 製作者名

DESCRIPTION OF DEFECT:不適合状態

TYPE:型式

COMMERCIAL NAME: 通称名

MODEL YEAR RECALLED:対象車両の製作年

NUMBER OF VEHICLE:対象車両数