## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	4420	DATE	February 1. 2019			
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.					
DESCRIPTION OF DEFECT	In the fuel hose of agricultural combine harvester, the tightnening torque of the hose band is inappropriate, there is a thing with scratches in the hose. Therefore, if you continue to use it in that state, cracks will enter the fuel hose due to vibration etc. In the worst case, fuel may leak.					

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED				
	「AG6100」	2012~2013	2012~2013 369		69	
ECR-C114	「AG6114」	2011~2013		40	404	
	[AG7114]	2011~2013	128			
	「AG6100R」	2014~2017	901			
-	「AG6114R」	2014~2017	524			
	[AG7114R]	2014~2017	60			
-	ГҮН6101]	2017~2018	110		10	
_	ГҮН6115]	2017~2018	2017~2018 87		7	
	ГҮН7115]	2017~2018	9			
	「YH460」	2015~2018	418			
-	「YH470」	2015~2018 422		22		
	「YH570」	2015~2018	589			
-	「YH590」	2015~2017	494			
				TOTAL	4,515	