## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4438	DATE	Feb. 7. 2019	
MANUFACTURER	Hino Motors, Ltd.			
DESCRIPTION OF DEFECT	As for the folding slope ramp installed at the foot of the middle entrance of the bus, the dimensions of the parts of the flip-up grab are incorrect. Therefore, some grab portions of the flip-up grabs keep sticking up when the user pulls up the grab portions, potentially causing passengers to trip over them and fall.			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-KR290J2	[HINO Rainbow]	2016~2017	214
2KG-KR290J3		2017~2018	180
QDG-KV290N1	[HINO Blue Ribbon]	2015~2017	355
QKG-KV290N1			
2DG-KV290N2		2017~2018	124
2KG-KV290N2			
QKG-KV290Q1		2015~2017	250
QPG-KV290Q1			
QRG-KV290Q1			
2KG-KV290Q2		2017~2018	83
2PG-KV290Q2			
2TG-KV290Q2			
QSG-HL2ANAP	[HINO Blue Ribbon Hybrid]	2015~2017	63
2SG-HL2ANBP		2017~2018	41
QSG-HL2ASAP		2015~2017	39
2SG-HL2ASBP		2017~2018	36
		TOTAL	1, 385