

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4433	DATE	February 14,2019
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Due to sulfur gas generated from intake rubber hose, the resistors inside the Air Flow Sensor may corrode and disconnected. As a result, causing the EV system warning lamp to turn on and the driving motor power to be restricted by the fail-safe control, further the engine may not be able to start. In this condition, the main drive battery not to be charged and the battery may be used up, and finally the vehicle may stop.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DLA-GG2W	「OUTLANDER PHEV」	2013~2014	11,413
TOTAL			11,413

Number of vehicles in which the service part is installed

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DLA-GG2W	「OUTLANDER PHEV」	2014~2015	5
TOTAL			5

The parts for which the vehicle can not be identified because it was shipped as service parts

Part Name	Part No.	Delivery Period of the part	Quantity
AIR FLOW SENSOR	1525A031	2013~2014	9