

CAMPAIGN No.	4534	DATE	2019.7.17		
MANUFACTURER	HANTA MACHINERY CO. LTD.				
DESCRIPTION OF DEFECT	On hydrostatic transmission of asphalt pavers, manufacturing procedure of check valve in hydraulic circuit is inappropriate and causes malfunction, a cas pressure of travel pump may go beyond the permissible value when starting the engine, and a seal of travel pump may change the shape, then its seal may be excess contact to pump shaft. Therefore, if repeating engine start, that seal will wear and oil will leak, and then machine may be caused out of travel in the worst case.				

	Т			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
YDN-F45W5	「Asphalt Finisher」	2017~2019		153
YDN-A45WD	「Asphalt Finisher」	2017~2019		229
			TOTAL	382