

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4594	DATE	October 31, 2019
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the certain passenger airbag inflator, some propellants in inflator may deteriorate due to the prolonged exposure to temperature cycling under humid condition. Therefore, during the airbag deployment, the container of inflator may be broken.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LA-SE3P	Mazda 「RX-8」	2003	72
LA-GG3P UA-GG3P	Mazda 「ATENZA」	2002-2005	2,165
LA-GG3S UA-GG3S		2002-2005	7,376
LA-GY3W UA-GY3W		2002-2005	9,576
LA-GGEP UA-GGEP CBA-GGEP		2002-2005	2,350
LA-GGES UA-GGES CBA-GGES		2002-2005	947
LA-GYEW UA-GYEW CBA-GYEW		2002-2005	1,123
		TOTAL	