

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4640	DATE	Jan. 16 , 2020
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	Due to the improper prevention of moisture absorption into propellant for passenger-side airbag inflator, propellant could degrade under the cycle of temperature and humidity. As a result of propellant degradation, inflator housing may rupture during airbag deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
LA-GD2	「IMPREZA」	2004 ~ 2007	653	
LA-GD3		2004 ~ 2007	405	
TA-GDA		2004 ~ 2007	1,249	
GH-GDB		2004 ~ 2007	2,725	
DBA-GDC		2006 ~ 2007	58	
DBA-GDD		2006 ~ 2007	36	
LA-GG2		2004 ~ 2007	4,149	
LA-GG3 TA-GG3		2004 ~ 2007	2,190	
TA-GG9		2004	15	
TA-GGA		2004 ~ 2007	553	
DBA-GGC		2006 ~ 2007	360	
DBA-GGD		2006 ~ 2007	218	
		TOTAL	12,611	