

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4641	DATE	Jan. 16, 2020
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	Due to an improper adjustment of assembling equipment, the spring used for the seat belt lock mechanism may have crookedly been installed for the rear center seating position seat belt. Therefore, the spring may interfere with structural parts, and the seat belt may not be locked when it is quickly pulled out.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GK2	「IMPREZA」	2019	49
DBA-GK3		2019	37
DBA-GK6		2019	34
DBA-GK7		2019	30
		TOTAL	150