VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic /Import Vehicles

CAMPAIGN No.	Gai-2968	DATE	16/January/2020
MANUFACTURER	Automobiles Volvo Car Corporation		
	(Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	There is an excessive soot build up that may result in intake valve leakage. Therefore the plastic engine intake manifold may deform. In the very worst case there is a possibility that a localized engine bay fire may occur. The corrective action is re-build EGR circuit and download improved ECM software. ECM Upgrade will implement an intake valve leakage diagnostic function.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[\$60]	2016-2017	248
VOLVO	[V60]	2016-2017	756
VOLVO	[XC60]	2016–2017	752
V0LV0	[V60CC]	2016-2017	277
VOLVO	[V40]	2016-2017	1017
VOLVO	[V40CC]	2016-2017	329
		Т01	TAL 3, 379