

**VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN**

Domestic Vehicles

CAMPAIGN No.	4645	DATE	Jan.22.2020
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the driver airbag inflator of the subject vehicle, due to insufficient protection against moisture absorption, there is a possibility that the propellant could absorb moisture. In this condition, if the propellant is used under the exposure to desiccation and moisture absorption repeatedly overtime, this could result in an abnormal airbag deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GF-SCP10	[Vitz]	1998-1999	5,367
GH-NCP10		1999	2
GH-NCP15		1999	1
E-AE101G	[COROLLA]	1997-1999	432
E-AE101	[COROLLA CERES] [SPRINTER MARINO]	1997-1998	32
E-AE111	[COROLLA] [COROLLA LEVIN] [SPRINTER] [SPINTER TRUENO]	1997-1999	2,197
E-AE111N GF-AE111N	[COROLLA SPACiO]	1998-1999	323
GF-AE115N			63
E-AE111G	[SPRINTER CARIB]	1997-1999	266
E-AE114G		1999	3
E-SXA10G GF-SXA10G E-SXA10W E-SXA10C GF-SXA10C	[RAV4 J] [RAV4 L]	1997-1999	650
E-SXA11G E-SXA11W			1,242

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
E-SXA15G GF-SXA15G	[RAV4 J] [RAV4 L]	1997-1999	435
E-SXA16G GF-SXA16G			474
BEA11G	[RAV4 EV]	1997-1999	99
E-ST210G	[CALDINA]	1998-1999	653
E-ST215G E-ST215W		1997-1999	1,806
E-ST202 E-ST202C	[CELICA]	1997-1999	1,333
E-ST205		1997-1999	415
E-SW20	[MR2]	1997-1999	1,490
E-JZA80	[Supra]	1997-1999	1,232
E-EP91	[STARLET]	1997-1999	1,095
E-EP95		1998-1999	8
GF-EXZ10	[RAUM]	1998-1999	409
GF-EXZ15			89
KD-KZN185W KH-KZN185W	[HILUX SURF]	1997-1999	167
GF-RZN180W		1998-1999	4
E-RZN185W GF-RZN185W GH-RZN185W		1997-1999	81
GF-VZN180W		1998-1999	2
E-VZN185W GF-VZN185W		1997-1999	97
E-EL52 E-EL52C	[CYNOS]	1997-1999	221
E-EL54 E-EL54C			94
E-AT210 GF-AT210	[CARINA]	1998-1999	163
		TOTAL	20,945