VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4642	DATE	Jan 23, 2020	
MANUFACTURER	SUZUKI MOTOR CORPORATION			
DESCRIPTION OF DEFECT	Due to improper material of plating on the movable contact terminal used on the horn switch, it can lead corrosion on contact surface of terminals by entering water or dust. If the switch is used in this condition continuously, it causes the electric discontinuity of contact points and hone may not work properly.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBJ-CE47A	Address 110	2015-2017	31,856
2BJ-CE47A		2018-2019	11,756
		TOTAL	43,612