

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No	4644	DATE	23th - January -2020
MANUFACTURER	Yano Special Vehicle Co., Ltd. 4-2-1 Kaminofukita Shingu Kasuya-Gun, Fukuoka 811-0123 Japan		
DESCRIPTION OF DEFECT	In a vehicle transport trailer, the rigidity of a bracket to which an EBS unit is attached is insufficient, so that a crack may be generated in a joint portion of a brake air pipe connected to the unit due to vibration or the like during traveling. Therefore, if the air conditioner is continued to be used as it is, an air leak occurs, a warning light is turned on, and in the worst case, the braking force may be reduced.		
TYPE	COMMERCIAL NAME	MODEL TEAR RECALLED	NUMBER OF VEHICLE
ARSTC100	-	001~012	12
ARSTC101		001~006	6
ARSTC103		001~002	2
			TOTAL 20