

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2973	DATE	January 23, 2020
MANUFACTURER	HONDA CANADA INC.		
DESCRIPTION OF DEFECT	Driver's airbag inflator is inadequately prevented from absorbing moisture whereby gas generating propellant contained therein may absorb moisture. Should gas generating propellant be moisturized and dried repeatedly while the vehicle continues in service, the inflator could fail to properly inflate the airbag in the event of airbag deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-RL1	「LAGREAT」	1999	357
		TOTAL	357