

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4655	DATE	27 Jan , 2020
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	Road maintenance vehicles are equipped with yellow flashing lamps. The mounting bolts of some of those yellow flashing lamp covers are not installed because of improper instructions for manufacturing process. Therefore, the yellow flashing lamp covers with no mounting bolts may fall off due to vehicle vibration during travel and may hinder the safety of other traffic.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDP-WA138	「WA100-8」	2019	48
YDR-WA137	「WA200-8」	2019	61
YDR-WA136	「WA270-8」	2019	59
YDP-WA135	「WA320-8」	2019	16
YDS-WA130	「WA380-8」	2019	18
YDS-GD032	「GD675-6」	2019	69
		TOTAL	271