

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4649	DATE	Jan.29.2020
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the driver's seat belt reminder system, due to an improper assembly of the electrical contacts in the reminder switch, there is a possibility that abnormal wear at the contacts may occur after repeated operation of the seat belt and residue may be deposited. In this condition, the seat belt reminder could not be released even when the seat belt is correctly fastened due to a short circuit between the contacts.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-ZVW50	[PRIUS]	2015-2018	192,893
DAA-ZVW51		2015-2019	108,756
DAA-ZVW55		2015-2018	57,372
DLA-ZVW52	[PRIUS PHV]	2016-2018	29,101
DAA-ZVW40W	[PRIUS α]	2014-2019	7,634
DAA-ZVW41W			23,029
DAA-ZVW41N	[MEBIUS]		144
		TOTAL	418,929