

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2977	DATE	Jan.29.2020
MANUFACTURER	TMMF (TOYOTA)		
DESCRIPTION OF DEFECT	On the vehicles equipped with supercharged engine, due to an improper material of the resin spacer attached to fuel pipe (delivery pipe), there is a possibility that the spacers could be deformed by heat etc., causing the securing bolts to become loose, and the bolts could break on the condition such as engine vibration. This could lead to a loss of injector sealing, resulting in fuel leakage, and in the worst case, vehicle fire could occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-NCP131-	[Vitz]	2017-2018	214
		TOTAL	214