

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4648	DATE	January 30, 2020.
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the certain driver air bag inflator, some propellants in inflator may absorb the moisture and degrade. Therefore, the air bag may not deploy properly in the event of air bag deployment. If the worst happens, the container of inflator may be broken.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
E-TA5P GF-TA5P	Mazda 「EUNOS 800」	1996-1997	3,762
E-TA5A		1996-1997	149
E-TA3P GF-TA3P		1996-1997	132
E-TA3A GF-TA3A		1996-1997	56
E-TA5P GF-TA5P	Mazda 「MILLENNIA」	1997-1999	4,939
E-TA5A		1997-1998	87
GF-TA5P		1998-1999	4,153
E-TA3P GF-TA3P		1997-1999	281
E-TA3A GF-TA3A		1997-1999	173
		TOTAL	13,732