

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2981	DATE	January 30,2020
MANUFACTURER	Mitsubishi Motors(Thailand)Co., Ltd.		
DESCRIPTION OF DEFECT	With regard to Driver's Side Airbag Inflator, the gas generating agent may absorb moisture due to improper moisture prevention. In some occasion for instance where gas generating agent gets moisture and dried out repeatedly, improper deployment may take place when the airbag is activated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KC-K74T	「STRADA」	1998~1999	43
		TOTAL	43