

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4 6 5 4	DATE	F e b . 0 4 . 2 0 2 0
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Some center stands are insufficient in strength due to improper welding specification for the left side welding between the arm and the cross tube. For that reason, if the center stand is repeatedly operated to stand up the vehicle, the said welding portion may be cracked, in the worst case, the welded portion will break. There is a risk that the vehicle will tip over when user operates the center stand.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2 B L - S J 1 5 J	XP530SA TMAX	2 0 1 7 ~ 2 0 1 9	1 4 1
	XP530DA TMAX	2 0 1 7 ~ 2 0 1 9	9 7 3
		TOTAL	1, 1 1 4