

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4652	DATE	February 6, 2020.
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the LED headlights, due to the inappropriate material of the gasket attached to the connector, the gasket gives off sulfur, which may corrode the LED circuit. If the corrosion of the circuit develops, the circuit may break down, causing front position light not to illuminate.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-KE2AW	Mazda 「CX-5」	2014-2015	9,716
LDA-KE2FW		2014-2015	12,407
DBA-KEEFW		2014-2015	2,916
DBA-KE5AW		2014-2015	1,013
DBA-KE5FW		2014-2015	766
		TOTAL	26,818