

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 6 5 8	DATE	Feb. 6. 2020
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	In the fuel hose of the vehicle with 2.0L turbo gasoline engine, due to inappropriate material of fuel hose, it may deteriorate early by heat. Therefore, if the driver continue to drive in this condition, the fuel may seep at cold start from connection of high-pressure fuel pump and fuel hose of low-pressure side.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-YV37	SKYLINE	2 0 1 4	5, 659
DBA-ZV37		~ 2 0 1 7	3, 155
		TOTAL	8, 814