

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4665	DATE	Feb.12.2020
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the ring gear assembled in the transfer used for the four-wheel drive vehicles, due to improper heat treatment, there is a possibility that the ring gear may not have a sufficient strength. In this condition, the gear could damage if the vehicle is operated repeatedly under the high-load condition, such as sudden start operation, resulting in the vehicle becoming inoperative.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QDF-GDH206V	[HIACE]	2019	3
CBA-TRH219W			1
		TOTAL	4