

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4636	DATE	February 13,2020
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	In the vehicle with the navigation system installed at the factory, due to an improper work operation during the production process of the IC for the liquid crystal display power supply, a liquid chemical which is not normally used may be remained. This can cause an open circuit inside the IC during use and the power will not be supplied to the liquid crystal display. As a result, the navigation monitor may not be displayed the direct front and left view, which may not conform to Japanese Safety Regulations for Road Vehicles, Article 44 (Rear-View-Mirror, etc.)		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DLA-GG2W	「OUTLANDER PHEV」	2013	2,546
DBA-GF7W	「OUTLANDER」	2013	5
DBA-GF8W		2013	106
LDA-CV1W	「DELICA」	2014	762
DBA-CV2W		2014	47
DBA-CV5W		2014	242
		TOTAL	3,708

Number of vehicles in which the service part is installed

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DLA-GG2W	「OUTLANDER PHEV」	2013~2014	33
DBA-GF8W	「OUTLANDER」	2013	1
LDA-CV1W	「DELICA」	2013~2014	7
DBA-CV5W		2014	1
		TOTAL	42