

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic

CAMPAIGN No.	4669	DATE	February 13, 2019	
MANUFACTURER	UD Trucks Corporation			
DESCRIPTION OF DEFECT	Due to the inappropriate material for the air dryer's compressed-air-pressure-test-connector for heavy-duty-trucks, the particular components contained within the compressed air, and high pressure generated from the compressor may cause corrode and crack in the connector, which may lead to compressed air leakage. Consequently, the compressed air supply becomes insufficient as the crack exacerbates, hence, causing the air pressure low warning lamp and buzzer to activate. In the worst case scenario, the parking brake may become unreleasable, which could lead to the vehicle becoming inoperable.			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-CD4BA	Quon	2018 - 2019	4	
2PG-CD4CA		2018 - 2019	13	
2PG-CD5AL		2017 - 2019	19	
2PG-CD5BA		2017 - 2019	185	
2PG-CD5BL 2PG-CD5BLKai		2017 - 2019	201	
2PG-CD5CA 2PG-CD5CAKai		2017 - 2019	2,688	
2PG-CD5CE		2018 - 2019	251	
2PG-CD5CL		2017 - 2019	228	
2DG-CF5AL		2018 - 2019	86	
2PG-CG4CA		2018 - 2019	10	
2PG-CG5BA		2017 - 2019	33	
2PG-CG5BE 2PG-CG5BEKai		2018	4	
2PG-CG5BL		2018 - 2019	3	
2PG-CG5CA		2017 - 2019	4,680	
2PG-CG5CE		2018 - 2019	307	
2PG-CG5CL		2017 - 2019	217	
2PG-CV4AA		2019	3	
2PG-CW4AL		2018 - 2019	39	
2PG-CW5AL		2017 - 2019	1,213	

2PG-CW5BL 2PG-CW5BLKai	Quon	2017 - 2019	314		
2PG-CW5CA 2PG-CW5CAKai		2017 - 2019	217		
2PG-CW5CL 2PG-CW5CLKai		2017 - 2019	297		
2PG-CX5BA 2PG-CX5BAKai		2017 - 2019	96		
2PG-CX5BL		2017 - 2019	63		
2DG-CZ5BL 2DG-CZ5BLKai		2018 - 2019	285		
2PG-GK5AAB 2PG-GK5AABKai		2017 - 2019	2,111		
2PG-GK5AAD		2017 - 2019	716		
2PG-GK5AAE		2017 - 2019	147		
2PG-GK5AAK		2018 - 2019	2		
2DG-SF5AL		-	2018	2	
2DG-SZ5BL			2018 - 2019	5	
2DG-HF5AL			2018	2	
2DG-HZ5BL			2018	3	
	TOTAL			14,444	