

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4647	DATE	Feb.14 2020
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some medium-duty trucks with a 4V20 engine, the turbocharger mounting nuts are not tightened to the specified torque due to improper tightening work. For this reason, exhaust gas may leak from the turbocharger mounting portion and cause abnormal noise.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FK61N	「FUSO FIGHTER」	2018~2019	27
2PG-FK64N		2018~2019	12
2PG-FK64NA		2019~2019	2
2PG-FK71N		2018~2019	65
2PG-FK71NA		2018~2019	11
2PG-FK74N		2018~2019	10
		TOTAL	127