

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4662	DATE	Feb.14,2020
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	<p>On the designated wheel crane engines manufactured as spare parts, there are cases where the turbocharger installation nut is not tightened to the proper torque due to improper tightening processes. Therefore, there is a risk of exhaust gas leaking from the turbocharger installation and abnormal noise.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
SC-TR120	TADANO 「PITAGORAS」	2006	1
		TOTAL	1