

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4657	DATE	February 18, 2020
MANUFACTURER	Mitsubishi Logisnext Co., Ltd		
DESCRIPTION OF DEFECT	A coil in the driver side display control board may have cracks inside caused by vibration during operation due to improper fixing instructions. Therefore, continued use under the condition might cause the coil's disconnection and the traction motor would stop operating.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
244AA	「TRANSER」	2018 ~ 2019	3
254AA		2018 ~ 2019	4
		TOTAL	7