

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4 6 7 0	DATE	F e b . 1 8 . 2 0 2 0
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	In the connection part of the fuel hose, since the application instruction of the adhesive agent was improper, there are some cases where the adhesion of the connection part is insufficient. Therefore, when a high fuel pressure is applied to the connection part, the airtightness of the connection part can be impaired, there is a possibility that the fuel leaks.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
E B L - V H 0 2 J	XVS400 DragStar	2 0 0 9 ~ 2 0 1 7	2 , 8 6 5
	XVS400C DragStar Classic	2 0 0 9 ~ 2 0 1 7	3 , 1 8 7
		TOTAL	6 , 0 5 2