

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4678	DATE	February 27, 2020
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Fuse box may incorporate a back-up light control relay which was an inappropriate choice. In this case, metallic particles can be generated by the relay actuation and can be caught in the relay actuator. Should this happen, electrical continuity of the relay could be lost, causing the back-up lights to fail to come on.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-JF3	「N-BOX」	2017-2019	133,702
DBA-JF4			24,051
HBD-JJ1	「N-VAN」	2018	19,730
HBD-JJ2		2018-2019	8,419
		TOTAL	185,902