## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Import Vehicles

CAMPAIGN No.	Gai-2993	DATE	February 27th, 2020
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	On the transmission wiring harness, it may affected by heat from the transmission due to improper rooting which could lead to squeezing of the wiring harness. For this reason, some wires in the transmission wiring harness may be melted and, in the worst case, short circuit then lit warning light and shifted to the emergency mode.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-JF44M	BMW M5	2018 - 2019	18
		TOTAL	18