

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2995	DATE	February 27 th , 2020
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The capacitor of the headlight control unit might be pre-damaged due to inappropriate seizing of the printed circuit board at the supplier. This could lead to short circuit by vehicle vibration and thermal stress. If a short circuit occurs, the headlight control unit for the left side might be shut-off and the headlight including the turn indicator may lose its function.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-HF20	BMW Z4 sDrive20i	2019	1
TOTAL			1