

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4638	DATE	Feb 28, 2020
MANUFACTURER	HANAMIDAI AUTO, co,ltd		
DESCRIPTION OF DEFECT	In some trailer braking devices, the push rod length of the spring brake chamber (distance from the mounting surface to the center of the joint pin) is improperly designated, so that the push rod length is relatively long. Therefore, there is a possibility that the braking force is not sufficiently generated.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
HDD220	Dump semitrailer	2013	1
		2014	2
		2016	1
HCD243	Container semitrailer	2016	2
		TOTAL	6