

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	4 6 8 0	DATE	4 MAR. 2020
MANUFACTURE	MARUYAMA MFG.CO.,INC		
DESCRIPTION OF DEFECT	In the wiring of the DPF temperature sensor of the agricultural chemical sprayer, there is a case in which the protection member of the wiring is in contact with the exhaust pipe due to an inappropriate mounting instruction of the wiring. Therefore, the wiring may be disconnected due to running vibration or the like, and the warning light may be turned on.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
MARUYAMA	SSA-V602	2018~2019	50
	SSA-V602-DX		
		TOTAL	50