

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 6 8 1	DATE	Mar.5.2019
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>In the circuit board of the power supply distributor, due to the inappropriate production process, in some circuit boards, moisture-proof material was coated with unnecessary solder attached to the board, and in a use process, some cracks may occur in the coating. Therefore, the minute conduction will be generated and an electrode ingredient moves under high humidity environment, and if a short circuit is formed, in an extreme case, it may lead to thermal incident on a vehicle by the heating of the short circuit electric current.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBF-VM20	NV200 VANETTE	2016	1
		TOTAL	1

The affected parts shipped as repair parts, but the vehicles installed them cannot be identified.

PARTS NAME	PARTS NO.	DELIVERLY YEAR	QUANTITY	Note
Power supply distributor	284B7-1F0D	2019	2	
	284B7-JX00B	2019	2	
		Total	4	