

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No..	4694	DATE	March-26-2020
MANUFACTURER	PABCO CO.,LTD		
DESCRIPTION OF DEFECT	In some fuel tanks , the drain plug is not properly tightened/ attached. Continued use of the tank in such a condition may cause fuel to leak from the drain plug.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FK62F	FUSO FIGHTER	2019	1
2KG-FK65FZ		2019	5
2KG-FK72FZ		2019	1
2PG-FRR90S2	ISUZU FORWARD	2019	1
2PG-FTR90V2		2019	1
2RG-FRR90S2		2019	2
2PG-FE2ABG	HINO RANGER	2019	2
2PG-FD2ABA		2019	1
2PG-FD2ABG		2019	1
2PG-GD2ABA		2019	2
2PG-FW1AHJ	HINO PROFIA	2019	1
2RG-FR1AHJ		2019	1
		TOTAL	19