

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

| | | | |
|-----------------------|---|------|---------------|
| CAMPAIGN No. | 4695 | DATE | Mar. 26. 2020 |
| MANUFACTURER | NIPPON FRUEHAUF COMPANY LIMITED | | |
| DESCRIPTION OF DEFECT | In some fuel tanks, the drain plug is not properly tightened due to improper assembly of the drain plug into the fuel tank. Therefore, if the fuel cell is continuously used as it is, fuel may leak from the drain plug. | | |

| MANUFACTURER'S NAME | TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|---------------------|-------------|-----------------|---------------------|-------------------|
| ISUZU | 2PG-FRR90S2 | FORWARD | 2019 | 2 |
| ISUZU | 2PG-FRR90T2 | FORWARD | 2019 | 1 |
| ISUZU | 2PG-FTR90V2 | FORWARD | 2019-2020 | 2 |
| ISUZU | 2RG-FRR90S2 | FORWARD | 2019 | 5 |
| ISUZU | 2RG-FRR90T2 | FORWARD | 2019 | 3 |
| ISUZU | 2RG-FSR90S2 | FORWARD | 2019 | 2 |
| ISUZU | 2RG-FTR90V2 | FORWARD | 2019 | 1 |
| HINO | 2KG-FC2ABA | HINO RANGER | 2019 | 4 |
| HINO | 2KG-FC2ABG | HINO RANGER | 2019 | 2 |
| HINO | 2KG-FD2ABA | HINO RANGER | 2020 | 1 |
| HINO | 2KG-FD2ABG | HINO RANGER | 2019 | 1 |
| HINO | 2KG-GD2ABG | HINO RANGER | 2019 | 1 |
| HINO | 2PG-FD2ABA | HINO RANGER | 2019 | 2 |
| HINO | 2PG-FD2ABG | HINO RANGER | 2019-2020 | 5 |
| HINO | 2PG-FE2ABG | HINO RANGER | 2019 | 2 |
| UD TRUCKS | 2PG-BRR90T2 | CONDOR | 2019 | 1 |
| UD TRUCKS | 2RG-BRR90S2 | CONDOR | 2019 | 1 |
| UD TRUCKS | 2PG-CD5CA | QUON | 2019 | 1 |
| | | | Total | 37 |