VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	GAI-3005	DATE	Mar.26,2020		
MANUFACTURER	TADANO LTD.				
DESCRIPTION OF DEFECT	The strength of some crane door frame-mounted side under-mirror mounting portion is insufficient due to inappropriate design instructions. Therefore, with repetition of the traveling vibration, door frame side under-mirror mounting portion may crack and, in the worst cases, may fall off.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
FAUN	$\lceil ext{ATF130G-5} floor$	2019	1
FAUN	「ATF200G-5」	2018-2019	7
FAUN	「ATF220G-5」	2018-2020	19
		TOTAL	27