

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/ Vehicles

CAMPAIGN No.	4690	DATE	Mar. 27th, 2020
MANUFACTURER	Yokohama Sharyo Kogyo Co.,Ltd.		
DESCRIPTION OF DEFECT	In the tractor, since the mounting position of the intermediate fender stay installed between the two rear axles is inappropriate, the fender stay and the U-bolt of the rear shock absorber come into contact when traveling on rough roads and the U-bolt is damaged. There is a risk.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QDG-EXZ52BJ	GIGA	2015	27
QKG-EXZ52BJ	GIGA	2015	15
2DG-EXZ52CK	GIGA	2018	28
2PG-EXZ52CK	GIGA	2018	6
		TOTAL	76