

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4724	DATE	April 2 ,2020
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		In the exhaust gas diffusing prevention devices of the heavy-duty trucks, the urea hoses may be deformed and damaged by the heat of the DPD (Diesel Particulate Defuser) due to the insufficient heat resistance of the hose. Consequently, if the trucks are continuously used without repair, urea might leak out, and nitrogen oxides (NOx) in the exhaust gas may exceed the emissions standards.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-CVR60C	[GIGA]	2017-2019	62
2KG-CVR77C 2PG-CVR77C		2017-2019	7
2KG-CXE60C		2018	3
2KG-CXE77C 2PG-CXE77C		2017-2019	52
2KG-CXG60CT		2018-2019	3
2KG-CXG77C 2PG-CXG77C		2017-2019	52
2KG-CXM60CT		2017-2019	57
2KG-CXM77C 2PG-CXM77C		2018-2019	7
2KG-CXY77CJ 2PG-CXY77CJ		2017-2019	75
2KG-CXZ60CT		2017-2019	285
2KG-CXZ77CT 2PG-CXZ77CT		2017-2019	3,299
2KG-CYE60CM		2017-2019	210
2PG-CYE77CZ		2017-2019	12
2KG-CYG60CM		2017-2019	321
2KG-CYH77C 2PG-CYH77C		2017-2019	252

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-CYJ77C 2KG-CYJ77CA 2PG-CYJ77C 2PG-CYJ77CA	[GIGA]	2017-2019	9,846
2PG-CYJ77CL		2017-2019	14
2DG-CYJ77CW		2018-2019	32
2KG-CYJ77CZ 2PG-CYJ77CZ		2017-2019	69
2KG-CYL60C		2017-2019	45
2KG-CYL77C 2KG-CYL77CA 2PG-CYL77C 2PG-CYL77CA		2017-2019	3,271
2KG-CYL77CM 2PG-CYL77CM		2017-2019	249
2KG-CYL77CZ 2PG-CYL77CZ		2017-2019	148
2KG-CYM77C 2PG-CYM77C		2017-2019	233
2KG-CYM77CM 2PG-CYM77CM		2017-2019	279
2KG-CYM77CZ 2PG-CYM77CZ		2018-2019	3
2KG-CYY60CY		2017-2018	2
2KG-CYY77C 2PG-CYY77C		2017-2019	314
2KG-CYY77CJ 2PG-CYY77CJ		2017-2019	87
2KG-CYY77CY 2PG-CYY77CY		2017-2019	374
2KG-CYZ77C 2PG-CYZ77C		2017-2019	459
2KG-CYZ77CJ 2PG-CYZ77CJ		2017-2019	140
2KG-CYZ77CM 2PG-CYZ77CM		2017-2019	731
2DG-CYZ77CMQ		2018-2019	3
2DG-CYZ77CV		2018-2019	7
		TOTAL	21,003