

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

| | | | |
|-----------------------|---|------|------------|
| CAMPAIGN No. | 4729 | DATE | Apr.8.2020 |
| MANUFACTURER | TOYOTA | | |
| DESCRIPTION OF DEFECT | In the brake master cylinder of the subject vehicles, due to an improper equipment used in the manufacturing process, there is a possibility that the direction of the rubber seal could not be correctly identified causing the seal to install in the reverse direction. In this condition, the lip of the seal may be damaged. If this occurs, the sealing performance of the lip could be degraded, resulting in the decrease of braking force in conditions where the brake pedal is depressed slowly. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-------------|-------------------|---------------------|-------------------|
| 3BA-ZRE212 | [COROLLA] | 2020 | 39 |
| 3BA-NRE210H | [COROLLA SPORT] | | 13 |
| 3BA-NRE214H | | | 2 |
| 3BA-ZRE212W | [COROLLA TOURING] | | 95 |
| | | TOTAL | 149 |