

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Imported Vehicles

CAMPAIGN No.	gai-3011	DATE	April 15 , 2020
MANUFACTURER	RENAULT SAS (Japanese Importer : Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	The wiring of electrical flap for Exhaust system will be burned out by radiant heat from surrounding exhaust parts and short circuit, which may cause it to be unable to restart by fuse blown due to excessive current. At the worst case, the engine may stall while driving and will not be able to restart.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-DFM5P	ALPINE A110	2018-2019	460
		TOTAL	460