

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Imported Vehicles

CAMPAIGN No.	gai-3012	DATE	April 15 , 2020
MANUFACTURER	RENAULT SAS (Japanese Importer : Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	Engine oil pressure solenoid valve, which is located at the engine bottom, may stick due to flown-down metal particles which have been produced in normal engine running. This incident may bring about noise from the engine, turning on a warning lamp, and at the worst case, engine broken.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-DFM5P	「ALPINE A110」	2018 - 2019	350
		TOTAL	350