

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	4737	DATE	27. APR. 2020
MANUFACTURER	NIPPON FRUEHAUF COMPANY LIMITED		
DESCRIPTION OF DEFECT	<p>In a medium-sized van truck, the exhaust gas may be directly applied because the mounting position of the side reflector is inappropriate. Therefore, the side reflector may be deformed due to the heat of the exhaust gas, and may not conform to The Safety Regulations Article 35-2 (standard of the side reflector).</p>		

MANUFACTURER'S NAME	TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ISUZU	2PG-FRR90S1	FORWARD	2018-2019	5
ISUZU	2PG-FRR90S2	FORWARD	2018-2019	16
ISUZU	2PG-FRR90T2	FORWARD	2018-2019	19
ISUZU	2RG-FRR90S2	FORWARD	2018-2019	40
ISUZU	2RG-FRR90T2	FORWARD	2018-2019	2
UD TRUCKS	2PG-BRR90S1	CONDOR	2019	1
UD TRUCKS	2PG-BRR90T2	CONDOR	2019	2
UD TRUCKS	2RG-BRR90S1	CONDOR	2018	1
			Total	86