

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4672	DATE	2020.4.28
MANUFACTURER	YANMAR CONSTRUCTION EQUIPMENT CO. ,LTD.		
DESCRIPTION OF DEFECT	There is a possibility that water encroach to the joint position since the stopping water treatment was not proper when they designed for shovel loader/wire harness. Therefore inside of the prevention connector is corroded and it can not energize. If they continue to use, there is a fear that LCD monitor and direction indicator will not light, the back buzzer will not work, engine will not start and the unit will not move back and forth.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDM-V37	「V3-7」	2015 to 2019	1151
YDM-V47	「V4-7」	2015 to 2019	1173
YDM-V57	「V5-7」	2015 to 2019	244
YDM-RW06	「LK40Z-6」	2015 to 2019	231
YDM-RX06	「LK50Z-6」	2015 to 2019	326
TOTAL			3125