

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4742	DATE	April 23,2020
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	Due to improper jigs which were used to punch the seat rail holes to adjust the seat positions, there are cases that the width of the holes is smaller than the regular ones on the driver or the rear seat rails. In such cases, the seats are not fixed properly and, in the worst case, the seats may move on the occasion of car collision, possibly causing the occupants to get unexpected injury.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5BA-LA650S	TANTO	2020	98
6BA-LA650S			
5BA-LA660S			22
6BA-LA660S			
5BA-LA650F	CHIFFON		46
6BA-LA650F			
5BA-LA660F			22
6BA-LA660F			
		TOTAL	188