

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

|                       |   |      |                    |
|-----------------------|---|------|--------------------|
| CAMPAIGN No.          | 4 7 4 4   | DATE | 1 2 . May. 2 0 2 0 |
| MANUFACTURER          | YAMAHA MOTOR CO., LTD.  |      |                    |
| DESCRIPTION OF DEFECT | <p>The nuts used to tighten the cylinder head of the engine are improperly machined, causing some threads of the nuts to damage.</p> <p>This causes insufficient tightening force of the cylinder head. During high engine load such as high-speed running, the airtightness of the cylinder head gasket will be impaired which may result in cooling water to penetrate into the combustion chamber. This may cause the spark plug to become wet and, in the worst case, the engine to stall or fail to start.</p> |      |                    |

| TYPE              | COMMERCIAL<br>NAME           | MODEL<br>YEAR<br>RECALLED | NUMBER OF<br>VEHICLE |
|-------------------|------------------------------|---------------------------|----------------------|
| J B K - S G 2 8 J | M A J E S T Y S<br>X C 1 5 5 | 2 0 1 4 ~ 2 0 1 7         | 1 2 , 9 2 4          |
|                   |                              | TOTAL                     | 1 2 , 9 2 4          |