VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

		D	omestic Import Vehicles	
CAMPAIGN No.	Gai-3027	DATE	May.13. 2020	
MANUFACTURE	BMW			
	(Japanese Importer: BMW Group Japan Corp.)			
DESCRIPTION OF DEFECT	The position of the throttle cable may cause an accumulation of water in the throttle cable sleeves that will not drain when driving C 400 models in the rain for an extended period of time or cleaning them thoroughly. When driving in out-side temperatures below freezing, this can lead to stiff movement up to the complete freezing of the throttle cables. Critical driving situations cannot be excluded under these conditions.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-C40AA	「BMW C400GT」	2019 - 2020	414
2BL-C40AA	「BMW C400X」	2019 - 2020	238
		TOTAL	652