

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

| | | | |
|-----------------------|---|------|-------------|
| CAMPAIGN No. | 4739 | DATE | May 14,2020 |
| MANUFACTURER | MITSUBISHI MOTORS CORPORATION | | |
| DESCRIPTION OF DEFECT | On the RH Front Lower Arm, parts were not fixed sufficiently in the welding process, the out of welding position of the parts were welded. Weld strength of the RH Front Lower Arm may not be sufficient. If the vehicle is continued to be used in this condition, the welded area may be peeled off due to a load when braking, which may result in unstable driving. | | |

| T Y P E | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|----------|-----------------|---------------------|-------------------|
| DBA-V83W | 「PAJERO」 | 2016~2018 | 125 |
| LDA-V88W | | 2016~2018 | 218 |
| DBA-V93W | | 2016~2018 | 246 |
| LDA-V98W | | 2016~2018 | 917 |
| | | TOTAL | 1,506 |

Number of vehicles in which the service part is installed

| T Y P E | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|----------|-----------------|---------------------|-------------------|
| LDA-V98W | 「PAJERO」 | 2016 | 1 |
| | | TOTAL | 1 |

The parts for which the vehicle can not be identified because it was shipped as service parts

| Part Name | Part No. | Delivery Period of the part | Quantity |
|------------------|----------|-----------------------------|----------|
| LOWER ARM KIT RH | 4013A210 | 2016~2018 | 63 |