

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4748	DATE	May.20.2020
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the front lower arms of the subject vehicles, due to an improper material production process, there is a possibility that the front lower arm(s) may have a crack. If the vehicle is driven in this condition, the crack propagates, and in the worst case, the lower arm(s) separates resulting in a loss of control the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6BA-MXAA52	[RAV4]	2019	231
6BA-MXAA54			1,966
6AA-AXAH52			188
6AA-AXAH54			1,024
		TOTAL	3,409